

1644Z 29 MAR 65

SECRET

1	DBA	9
2	DDBA	10
3	DFA	11
4	DEA	12
5	MD	13
6	"	14
7	DTech	15
8	RB	16

DIRECTOR

ROUTINE

IN 96448

OSA 1-20

TO

INFO

CITE

25X1A

25X1A

FOR: GEN. LEDFORD FROM: KELLY JOHNSON

SUBJ: ARTICLE 342 ACCIDENT INVESTIGATION

THE FINAL METALLURGICAL REPORTS ON ARTICLE 342 WILL BE
MAILED TODAY UNDER SEPARATE COVER.

PER YOUR VERBAL REQUEST, WE WILL ADD A CAUTION NOTE TO
THE FLIGHT MANUAL VN DIAGRAM AS FOLLOWS:

CAUTION

THE ABOVE VN DIAGRAM DEFINES THE AIRPLANE
CAPABILITY FOR SYMMETRICAL FLIGHT. HOWEVER,
ALL AIRCRAFT ARE TRADITIONALLY LIMITED TO A
REDUCTION IN THESE VALUES OF FROM 20 TO 33 PER CENT
FOR ABRUPT ACCELERATED OR MAXIMUM VELOCITY ROLL.

25X1A

FOR THE ABOVE CAUTION NOTE SHOULD BE
ADDED TO YOUR FLIGHT MANUALS IMMEDIATELY. WILL
ISSUE IDC'S ASAP.

25X1A

END OF MESSAGE